



## **DASA AD A30-2024-003 – ATA 53 - Fuselage Inspection of the Longitudinal Lap Joints Skin Splice Areas at S-4, S-14 & S-24**

DASA issues AD A30-2024-003 (WEF 20 Dec 24) requiring operators to undertake initial and repetitive inspections of the longitudinal lap joints skin splice areas at S-4, S-14 & S-24 for cracks on all RAAF E-7A aircraft.

For further information, contact: [dasadaveng.submission@defence.gov.au](mailto:dasadaveng.submission@defence.gov.au)

---

Past Newsbreaks located [DASA web site](#).

DASA Newsbreaks: Unsubscribe - send blank email to [DASA Unsubscribe](#)

DASA Newsbreaks: Subscribe - send blank email to [DASA Subscribe](#)

**Note:** DASA Newsbreak content is OFFICIAL and is intended as information only for Defence, contractor personnel, and other interested parties working in areas related to Defence aviation and space safety.

DASA only retains email addresses on the DASA Subscribe distribution list; this list will not be passed onto third parties.