



## **DASA AD A30-2024-002 – ATA 53 - Cracking of Forward Galley Door Cut-out Forward Upper Corner Fuselage Skin and Bear Strap AL1**

DASA issues AD A30-2024-002 (WEF 22 Nov 24) requiring operators to undertake initial and repetitive inspections of the forward galley door cut-out forward upper corner on all RAAF E-7A aircraft. This Newsbreak amendment corrects the identification of the AD.

For further information, contact: [dasadaveng.submission@defence.gov.au](mailto:dasadaveng.submission@defence.gov.au)

---

Past Newsbreaks located [DASA web site](#).

DASA Newsbreaks: Unsubscribe - send blank email to [DASA Unsubscribe](#)

DASA Newsbreaks: Subscribe - send blank email to [DASA Subscribe](#)

**Note:** DASA Newsbreak content is OFFICIAL and is intended as information only for Defence, contractor personnel, and other interested parties working in areas related to Defence aviation safety.

DASA only retains email addresses on the DASA Subscribe distribution list; this list will not be passed onto third parties.