



DASA-AD-A27-2024-001 through DASA-AD-A27-2024-004 – ATA 72 – Power Plant - Adour Mk. 951 - Various

DASA issues the following Airworthiness Directives which mandates action for the replacement of affected parts at or before a reduced life limit on the ADF Hawk Mk. 127 fleet with Adour Mk. 951 engine:

- DASA-AD-A27-2024-001 – ATA 72 – Power Plant – Adour Mk. 951 Module 08 Low Pressure Turbine Blades – Replacement
- DASA-AD-A27-2024-002 – ATA 72 – Power Plant – Adour Mk. 951 Module 01 Low Pressure Compressor Stage 1 Blade – Replacement
- DASA-AD-A27-2024-003 – ATA 72 - Power Plant – Adour Mk. 951 Module 01 Low Pressure Compressor Stage 2 Blade – Replacement
- DASA-AD-A27-2024-004 – ATA 72 - Power Plant – Adour Mk. 951 Module 01 Low Pressure Compressor Disc – Replacement

The effective date for these Airworthiness Directives is 16 December 2024.

If you have any questions, contact: dasadaveng.submission@defence.gov.au.

Past Newsbreaks located [DASA web site](#).

DASA Newsbreaks: Unsubscribe - send blank email to [DASA Unsubscribe](#)

DASA Newsbreaks: Subscribe - send blank email to [DASA Subscribe](#)

Note: DASA Newsbreak content is OFFICIAL and is intended as information only for Defence, contractor personnel, and other interested parties working in areas related to Defence aviation safety.

DASA only retains email addresses on the DASA Subscribe distribution list; this list will not be passed onto third parties.