



Australian Government
Department of Defence
Defence Aviation Safety Authority

Defence Aviation Safety Authority - **Newsbreak**

Capability First, Safety Always

DASA-AD-A15-2024-001 - ATA72 – T55-GA-714A 2nd Stg Gas Producer Rotor Assembly - Removal

DASA issues AD A15-2024-001 which mandates action for removal of affected parts at or before a reduced life limit on the ADF CH-47F fleet. The effective date for this AD is 12 April 2024.

If you have any questions, contact: dasadaveng.submission@defence.gov.au.

Past Newsbreaks located [DASA web site](#).

DASA Newsbreaks: Unsubscribe - send blank email to [DASA Unsubscribe](#)

DASA Newsbreaks: Subscribe - send blank email to [DASA Subscribe](#)

Note: DASA Newsbreak content is OFFICIAL and is intended as information only for Defence, contractor personnel, and other interested parties working in areas related to Defence aviation safety.

DASA only retains email addresses on the DASA Subscribe distribution list; this list will not be passed onto third parties.