



DASA AD A34-2025-002 Issue 1 – C-27J Frame 45 Cargo Door Hinge Beam Cracking

DASA issues AD A34-2025-002 Issue 1, which mandates action for the inspection, repair and rectification of Fuselage Frame 45 Cargo Door Hinge Beam cracking on the RAAF C-27J fleet.

The effective date of this Airworthiness Directive is 23 May 2025.

If you have any questions, contact: dasadaveng.submission@defence.gov.au.

Past Newsbreaks located [DASA web site](#).

DASA Newsbreaks: Unsubscribe - send blank email to [DASA Unsubscribe](#)

DASA Newsbreaks: Subscribe - send blank email to [DASA Subscribe](#)

Note: *DASA Newsbreak content is OFFICIAL and is intended as information only for Defence, contractor personnel, and other interested parties working in areas related to Defence aviation and space safety.*

DASA only retains email addresses on the DASA Subscribe distribution list; this list will not be passed on to third parties.