

OFFICIAL



DASA AD A34-2023-001 C-27J Shear Ties Frame 43 Cracking

DASA issues AD A34-2023-001 which mandates action for the inspection, repair and investigation of Fuselage Frame 43 cracking on the RAAF C-27J fleet. The effective date for this AD is 21 December 2023.

If you have any questions, contact: dasadaveng.submission@defence.gov.au.

Please do not reply to this email

To access DASA Newsbreaks that have previously been disseminated, please go to the DASA Internet.

To unsubscribe from DASA Newsbreaks, please send a blank email to DASA Unsubscribe

To subscribe someone else to DASA Newsbreaks, please have them send a blank email to DASA Subscribe

Note:

All DASA Newsbreak content is UNCLASSIFIED and intended only as information for Defence and contractor personnel, as well as other interested parties working in areas related to Defence aviation safety.

DASA only retains email addresses on the DASA Subscribe distribution list. Details in this list will not be passed on to third parties.