



A30-2020-001 Issue 02 - L-RHS OTBD Chords and Frame Fittings and Failsafe Straps at STA 663.75

DASA issues AD A30-2020-001 Issue 2, requiring operators to undertake initial and repetitive inspections of the LHS and RHS Outboard Chords, Frame Fittings and Failsafe Straps at Station 663.75. Issue 2 of this AD supersedes Issue 1, incorporates FAA AD 2025-07-03 and modifies reporting requirements.

For further information, contact: dasadaveng.submission@defence.gov.au

Past Newsbreaks located [DASA web site](#).

DASA Newsbreaks: Unsubscribe - send blank email to [DASA Unsubscribe](#)

DASA Newsbreaks: Subscribe - send blank email to [DASA Subscribe](#)

Note: *DASA Newsbreak content is OFFICIAL and is intended as information only for Defence, contractor personnel, and other interested parties working in areas related to Defence aviation and space safety.*

DASA only retains email addresses on the DASA Subscribe distribution list; this list will not be passed on to third parties.