



Australian Government  
Department of Defence  
Defence Aviation Safety Authority

Defence Aviation Safety Authority - **Newsbreak**

Capability First, Safety Always

## **DASA AD A34-2023-001 C-27J Shear Ties Frame 43 Cracking Issue 2**

DASA issues AD A34-2023-001 Issue 2 which mandates action for the inspection, repair and investigation of Fuselage Frame 43 cracking on the RAAF C-27J fleet. This AD supersedes the previous issue and the effective date is 26 March 2024.

If you have any questions, contact: [dasadaveng.submission@defence.gov.au](mailto:dasadaveng.submission@defence.gov.au).

---

**Past Newsbreaks are available on the [DASA web site](#).**

To unsubscribe from DASA Newsbreaks, please send a blank email to [DASA Unsubscribe](#)

To subscribe someone else to DASA Newsbreaks, please have them send a blank email to [DASA Subscribe](#)

**Note:**

*All DASA Newsbreak content is OFFICIAL and intended only as information for Defence and contractor personnel, as well as other interested parties working in areas related to Defence aviation safety.*

*DASA only retains email addresses on the DASA Subscribe distribution list. Details in this list will not be passed on to third parties.*