

DASA AD A30-2020-001 Cracking of L/RHS OTBD Chords and Frame Fittings and Failsafe Straps at STA 663.75 Issue 01

DASA issues AD A30-2020-001 Issue 01 which mandates action for the inspection of the outboard chords of station 663.75 frame fittings and failsafe straps due to cracking on the RAAF E-7A fleet. This AD supersedes the previous issue and the effective date is 29 July 2024.

If you have any questions, contact: <u>dasadaveng.submission@defence.gov.au</u>.

Please do not reply to this email

Past Newsbreaks located DASA web site.

DASA Newsbreaks: Unsubscribe - send blank email to DASA Unsubscribe

DASA Newsbreaks: Subscribe - send blank email to DASA Subscribe

Note: DASA Newsbreak content is OFFICIAL and is intended as information only for Defence, contractor personnel, and other interested parties working in areas related to Defence aviation safety.

DASA only retains email addresses on the DASA Subscribe distribution list; this list will not be passed onto third parties.